

Oscium Storage Spec

Temperature

Operating range: 5 to 50C

Non-operating range: -20C to 60C

Humidity

Operating range: 20-80% RH below 32C; derate upper limit to 21% at 50C

Non-operating range: 5-90% RH below 41C; derate upper limit to 30% RH at 60C

Altitude

Operating range: 3000m

Non-operating range: 15,000m

Pollution degree

2; Typical home or office environment

Drop resistance

Survives 30" drop onto concrete with only cosmetic damage



OSCIUM